

METHOD STATEMENT: Operation of Detectors – turning ON/OFF HV supply

M.S.-Remote-Power-013

11th October 2012

Description of task: HV supplies will be turned on using the switch on the front panel.

Risk Assessment: RemotePower-013

Task Procedure:

- 1) Ensure that HV connections on detectors are fenced off and/or are inaccessible.
- 2) Post warning sign on HV supply indicating that HV is powered ON.
- 3) Get power supply keys from “grey” keypress.
- 4) Turn on HV supply with keyswitch on front panel.
- 5) Disconnection of any cables or modules is forbidden while supply is powered ON.
- 6) After data-taking is completed, turn OFF supply using keyswitch on front panel, remove warning signs and return keys to keypress.